


SiPM tester upgrade



Balazs Ujvari 04.19.2017

Fix to replaceable SiPM



Inside

- Now the 2x2 SiPMs (fix) are on the bottom side of the black panel
- We will add a new panel, where the SiPMs will be on the top, we need to recable it, we started it.



Mechanical parts on the table

We have to build this structure and modify the code
Create howto about the measurement

